

DT-6F-X

PINOUT DIAGRAM

OPTICAL PORT

STATUS INDICATORS

1. POWER (GREEN)
2. NA

STATUS INDICATORS


1. TX CARRIER (GREEN)/ERROR (RED)

DATA RS422 (PORT 3) (DB-9 FEMALE)

1. (CH.1) INPUT +
2. (CH.1) INPUT -
3. (CH.2) INPUT +
4. (CH.2) INPUT -
5. GND
6. (CH.3) INPUT +
7. (CH.3) INPUT -
8. (CH.4) INPUT +
9. (CH.4) INPUT -

DATA RS422 (PORT 4) (DB-9 FEMALE)

1. (CH.5) INPUT +
2. (CH.5) INPUT -
3. (CH.6) INPUT +
4. (CH.6) INPUT -
5. GND
6. NA
7. NA
8. NA
9. NA



STATUS INDICATORS

1. NA
2. NA
3. NA

STATUS INDICATORS (PORT 3)

1. (CH.1) DATA INPUT
2. NA
3. (CH.2) DATA INPUT
4. NA
5. (CH.3) DATA INPUT
6. NA
7. (CH.4) DATA INPUT
8. NA

STATUS INDICATORS (PORT 4)

1. (CH.5) DATA INPUT
2. NA
3. (CH.6) DATA INPUT
4. NA
5. NA
6. NA
7. NA
8. NA

DR-6F-X

PINOUT DIAGRAM

STATUS INDICATORS

1. POWER (GREEN)
2. NA

STATUS INDICATORS


1. NA

DATA RS422 (PORT 3) (DB-9 FEMALE)

1. (CH.3) OUTPUT +
2. (CH.3) OUTPUT -
3. (CH.4) OUTPUT +
4. (CH.4) OUTPUT -
5. GND
6. (CH.3) OUTPUT +
7. (CH.3) OUTPUT -
8. (CH.4) OUTPUT +
9. (CH.4) OUTPUT -

DATA RS422 (PORT 4) (DB-9 FEMALE)

1. (CH.5) OUTPUT +
2. (CH.5) OUTPUT -
3. (CH.6) OUTPUT +
4. (CH.6) OUTPUT -
5. GND
6. NA
7. NA
8. NA
9. NA



OPTICAL PORT

STATUS INDICATORS

1. RX OPTICAL SIGNAL (GREEN)/ABSENT (RED)
2. NA
3. RX CARRIER (GREEN)/ERROR (RED)

STATUS INDICATORS (PORT 3)

1. NA
2. (CH.1) DATA OUTPUT
3. NA
4. (CH.2) DATA OUTPUT
5. NA
6. (CH.3) DATA OUTPUT
7. NA
8. (CH.4) DATA OUTPUT

STATUS INDICATORS PORT 4)

1. NA
2. (CH.5) DATA OUTPUT
3. NA
4. (CH.6) DATA OUTPUT
5. NA
6. NA
7. NA
8. NA