

FT-2W-X

PINOUT DIAGRAM

STATUS INDICATORS


PWR -POWER (GREEN)
 DIAG - CARD DIAGNOSTIC*
 (GREEN-OK, RED-ALARM)
 TX C/L -TX CARRIER (GREEN)
 /OVERLOAD (RED)

STATUS INDICATORS CH.1

SYN -SYNC PRESENT (GREEN)
 / LOAD ABSENT (RED)
 VIDEO -VIDEO PRESENT (GREEN)
 /OVERLOAD (RED)

STATUS INDICATORS CH.2

SYN -SYNC PRESENT (GREEN)
 / LOAD ABSENT (RED)
 VIDEO -VIDEO PRESENT (GREEN)
 /OVERLOAD (RED)



OPTICAL PORT IN/OUT
 (ST, FC)

VIDEO INPUT (CH.1)

VIDEO INPUT (CH.2)

FR-2W-X

PINOUT DIAGRAM

STATUS INDICATORS


PWR -POWER (GREEN)
 DIAG - CARD DIAGNOSTIC*
 (GREEN-OK, RED-ALARM)
 RX C/E -RX CARRIER (GREEN)
 /ERROR (RED)

STATUS INDICATORS CH.1

SYN -SYNC PRESENT (GREEN)
 / LOAD ABSENT (RED)
 VIDEO -VIDEO PRESENT (GREEN)
 /OVERLOAD (RED)

STATUS INDICATORS CH.2

SYN -SYNC PRESENT (GREEN)
 / LOAD ABSENT (RED)
 VIDEO -VIDEO PRESENT (GREEN)
 /OVERLOAD (RED)



OPTICAL PORT IN/OUT
 (ST, FC)

VIDEO OUTPUT (CH.1)

VIDEO OUTPUT (CH.2)