

ST-2C-X

PINOUT DIAGRAM

STATUS INDICATORS

PWR - POWER (GREEN)
 DIAG - NA
 TX C/L - TX CARRIER (GREEN)
 /OVERLOAD (RED)
 RX C/E - NA

SYN - NA

VID - NA

DR1 - (CH.1) CC INPUT
 DR2 - (CH.2) CC INPUT

AR1 - NA

AR2 - NA

CR1 - NA

CR2 - NA

DT1 - NA


DT2 - NA

AT1 - NA

AT2 - NA

CT1 - NA

CT2 - NA



OPTICAL PORT (ST, FC)

CC INPUT

1. (CH.1) GROUND
2. (CH.1) CC INPUT
3. (CH.2) GROUND
4. (CH.2) CC INPUT
5. GROUND

1. NA
2. NA
3. NA
4. NA

1. NA
2. NA
3. NA
4. NA
5. NA


SR-2C-X

PINOUT DIAGRAM

STATUS INDICATORS

PWR - POWER (GREEN)
 DIAG - NA
 TX C/L - NA
 RX C/E - RX CARRIER (GREEN)
 /ERROR (RED)
 SYN - NA
 VID - NA

DR1 - (CH.1) CC OUTPUT
 DR2 - (CH.2) CC OUTPUT
 AR1 - NA
 AR2 - NA
 CR1 - NA
 CR2 - NA
 DT1 - NA
 DT2 - NA
 AT1 - NA
 AT2 - NA
 CT1 - NA
 CT2 - NA



OPTICAL PORT (ST, FC)

CC OUTPUT

1. (CH.1) CC OUTPUT
2. (CH.1) CC OUTPUT
3. (CH.2) CC OUTPUT
4. (CH.2) CC OUTPUT
5. GROUND

1. NA
2. NA
3. NA
4. NA

1. NA
2. NA
3. NA
4. NA
5. NA