


ST-4D-XS

PINOUT DIAGRAM

STATUS INDICATORS

DR1 -	NA
DR2 -	NA
AR1 -	NA
AR2 -	NA
CR1 -	NA
CR2 -	NA
DT1 -	(CH.1) DATA INPUT
DT2 -	(CH.2) DATA INPUT
AT1 -	NA
AT2 -	NA
CT1 -	(CH.3) DATA INPUT
CT2 -	(CH.4) DATA INPUT



OPTICAL PORT (ST, FC) STATUS INDICATORS

PWR - POWER (GREEN)
 DIAG - NA
 TX C/L - TX CARRIER (GREEN) / OVERLOAD (RED)
 RX C/E - NA
 SYN - NA
 VID - NA

DATA INPUT

1. (CH.1) RS232 INPUT
2. (CH.2) RS232 INPUT
3. (CH.3) RS232 INPUT
4. (CH.4) RS232 INPUT
5. GND

SR-4D-XS


PINOUT DIAGRAM

STATUS INDICATORS

DR1 - (CH.1) DATA OUTPUT
 DR2 - (CH.2) DATA OUTPUT
 AR1 - NA
 AR2 - NA
 CR1 - (CH.3) DATA OUTPUT
 CR2 - (CH.4) DATA OUTPUT
 DT1 - NA
 DT2 - NA
 AT1 - NA
 AT2 - NA
 CT1 - NA
 CT2 - NA

OPTICAL PORT (ST, FC) STATUS INDICATORS

PWR - POWER (GREEN)
 DIAG - NA
 TX C/L - NA
 RX C/E - RX CARRIER (GREEN) / ERROR (RED)
 SYN - NA
 VID - NA



DATA OUTPUT

1. (CH.1) RS232 OUTPUT
2. (CH.2) RS232 OUTPUT
3. (CH.3) RS232 OUTPUT
4. (CH.4) RS232 OUTPUT
5. GND