


SX-2C1F/2C1F-XS

PINOUT DIAGRAM

STATUS INDICATORS

PWR - POWER (GREEN)
 DIAG - NA
 TX C/L - TX CARRIER (GREEN)
 / OVERLOAD (RED)
 RX C/E - RX CARRIER (GREEN)
 / ERROR (RED)




OPTICAL PORT INPUT (ST, FC)

OPTICAL PORT OUTPUT (ST, FC)

STATUS INDICATORS

DR1 - (CH.1) DATA OUTPUT
 DR2 - NA
 AR1 - NA
 AR2 - NA
 CR1 - (CH.1) C/C OUTPUT
 CR2 - (CH.2) C/C OUTPUT
 DT1 - (CH.1) DATA INPUT
 DT2 - NA
 AT1 - NA
 AT2 - NA
 CT1 - (CH.1) C/C INPUT
 CT2 - (CH.2) C/C INPUT



CC INPUT/OUTPUT (CH.2)

1. (CH.2) CC OUTPUT-
2. (CH.2) CC OUTPUT+
3. (CH.2) CC INPUT
4. (CH.2) GND
5. GND

CC INPUT/OUTPUT (CH.1)

1. (CH.1) CC OUTPUT-
2. (CH.1) CC OUTPUT+
3. (CH.1) CC INPUT
4. (CH.1) GND

DATA INPUT/OUTPUT

1. (CH.1) DATA INPUT -
2. (CH.1) DATA INPUT +
3. (CH.1) DATA OUTPUT-
4. (CH.1) DATA OUTPUT+
5. GND