

SX-2R/2R-X

PINOUT DIAGRAM

OPTICAL PORT OUTPUT (ST, FC)

OPTICAL PORT INPUT (ST, FC)


STATUS INDICATORS

PWR - POWER (GREEN)
 DIAG - FLASH (GREEN)/ERROR (RED)
 TX ERROR - NORMAL OFF/LASER DRIVER
 ERROR (RED)
 RX OPTIC - NORMAL OFF/OPTICAL SIGNAL
 ABSENT (RED)

10/100 ETHERNET INPUT/OUTPUT
 (RJ-45 FEMALE)

STATUS INDICATORS

TX 10 - 10 BASE-T DATA INPUT (GREEN)
 TX 100 - 100 BASE-T DATA INPUT (GREEN)
 RX 10 - 10 BASE-T DATA OUTPUT (GREEN)
 RX 100 - 100 BASE-T DATA OUTPUT (GREEN)
 TX DATA - DATA ACTIVITY INPUT (GREEN)
 RX DATA - DATA ACTIVITY OUTPUT (GREEN)



OPTICAL PORT OUTPUT (ST, FC)

OPTICAL PORT INPUT (ST, FC)

STATUS INDICATORS

PWR - POWER (GREEN)
 DIAG - FLASH (GREEN)/ERROR (RED)
 TX ERROR - NORMAL OFF/LASER DRIVER
 ERROR (RED)
 RX OPTIC - NORMAL OFF/OPTICAL SIGNAL
 ABSENT (RED)

10/100 ETHERNET INPUT/OUTPUT
 (RJ-45 FEMALE)

STATUS INDICATORS

TX 10 - 10 BASE-T DATA INPUT (GREEN)
 TX 100 - 100 BASE-T DATA INPUT (GREEN)
 RX 10 - 10 BASE-T DATA OUTPUT (GREEN)
 RX 100 - 100 BASE-T DATA OUTPUT (GREEN)
 TX DATA - DATA ACTIVITY INPUT (GREEN)
 RX DATA - DATA ACTIVITY OUTPUT (GREEN)