


SXA-4C/4C-XS

PINOUT DIAGRAM

STATUS INDICATOR

- 1 - (CH.1) CC INPUT
- 2 - (CH.2) CC INPUT
- 3 - (CH.3) CC INPUT
- 4 - (CH.4) CC INPUT
- 5 - NA
- 6 - NA
- 7 - NA
- 8 - NA
- 9 - (CH.4) CC OUTPUT
- 10 - (CH.3) CC OUTPUT
- 11 - (CH.2) CC OUTPUT
- 12 - (CH.1) CC OUTPUT



OPTICAL PORT (ST, FC)

STATUS INDICATORS

PWR - POWER (GREEN)

DIAG - NA

TX C/L - TX CARRIER (GREEN) / OVERLOAD (RED)

RX C/E - RX CARRIER (GREEN) / ERROR (RED)

SYN - NA

VID - NA

CC INPUT

- 1. (CH.1) CC INPUT
- 2. (CH.2) CC INPUT
- 3. (CH.3) CC INPUT
- 4. (CH.4) CC INPUT
- 5. GND

CC OUTPUT

- 1. (CH.1) CC OUTPUT-
- 2. (CH.1) CC OUTPUT+
- 3. (CH.2) CC OUTPUT-
- 4. (CH.2) CC OUTPUT+

CC OUTPUT


- 1. (CH.3) CC OUTPUT-
- 2. (CH.3) CC OUTPUT+
- 3. (CH.4) CC OUTPUT-
- 4. (CH.4) CC OUTPUT+
- 5. GND

SXB-4C/4C-XS

PINOUT DIAGRAM

STATUS INDICATORS

- 1 - (CH.1) CC INPUT
- 2 - (CH.2) CC INPUT
- 3 - (CH.3) CC INPUT
- 4 - (CH.4) CC INPUT
- 5 - NA
- 6 - NA
- 7 - NA
- 8 - NA
- 9 - (CH.4) CC OUTPUT
- 10 - (CH.3) CC OUTPUT
- 11 - (CH.2) CC OUTPUT
- 12 - (CH.1) CC OUTPUT



OPTICAL PORT (ST, FC)

STATUS INDICATORS

PWR - POWER (GREEN)

DIAG - NA

TX C/L - TX CARRIER (GREEN) / OVERLOAD (RED)

RX C/E - RX CARRIER (GREEN) / ERROR (RED)

SYN - NA

VID - NA

CC INPUT

- 1. (CH.1) CC INPUT
- 2. (CH.2) CC INPUT
- 3. (CH.3) CC INPUT
- 4. (CH.4) CC INPUT
- 5. GND

CC OUTPUT

- 1. (CH.1) CC OUTPUT-
- 2. (CH.1) CC OUTPUT+
- 3. (CH.2) CC OUTPUT-
- 4. (CH.2) CC OUTPUT+

CC OUTPUT

- 1. (CH.3) CC OUTPUT-
- 2. (CH.3) CC OUTPUT+
- 3. (CH.4) CC OUTPUT-
- 4. (CH.4) CC OUTPUT+
- 5. GND