

DXA-4K/4K-X

PINOUT DIAGRAM

STATUS INDICATORS

1. POWER (GREEN)
2. NA

STATUS INDICATORS

1. TX CARRIER (GREEN)/ERROR (RED)

DATA RS485 IN (PORT 3)


(DB-9 FEMALE)

1. (CH.1) INPUT+
2. (CH.1) INPUT-
3. (CH.2) INPUT+
4. (CH.2) INPUT-
5. GND
6. (CH.3) INPUT+
7. (CH.3) INPUT-
8. (CH.4) INPUT+
9. (CH.4) INPUT-

DATA RS485 OUT (PORT 4)

(DB-9 FEMALE)

1. (CH.1) OUTPUT+
2. (CH.1) OUTPUT-
3. (CH.2) OUTPUT+
4. (CH.2) OUTPUT-
5. GND
6. (CH.3) OUTPUT+
7. (CH.3) OUTPUT-
8. (CH.4) OUTPUT+
9. (CH.4) OUTPUT-



OPTICAL PORT

STATUS INDICATORS

1. NA
2. RX OPTICAL SIGNAL (GREEN)/ABSENT (RED)
3. RX CARRIER (GREEN)/ERROR (RED)

STATUS INDICATORS (PORT 3)

1. (CH.1) DATA INPUT
2. (CH.1) NA
3. (CH.2) DATA INPUT
4. (CH.2) NA
5. (CH.3) DATA INPUT
6. (CH.3) NA
7. (CH.4) DATA INPUT
8. (CH.4) NA

STATUS INDICATORS (PORT 4)

1. (CH.1) NA
2. (CH.1) DATA OUTPUT
3. (CH.2) NA
4. (CH.2) DATA OUTPUT
5. (CH.3) NA
6. (CH.3) DATA OUTPUT
7. (CH.4) NA
8. (CH.4) DATA OUTPUT

DXB-4K/4K-X

PINOUT DIAGRAM

STATUS INDICATORS

1. POWER (GREEN)
2. NA

STATUS INDICATORS


1. TX CARRIER (GREEN)/ERROR (RED)

DATA RS485 OUT (PORT 3) (DB-9 FEMALE)

1. (CH.1) OUTPUT+
2. (CH.1) OUTPUT-
3. (CH.2) OUTPUT+
4. (CH.2) OUTPUT-
5. GND
6. (CH.3) OUTPUT+
7. (CH.3) OUTPUT-
8. (CH.4) OUTPUT+
9. (CH.4) OUTPUT-

DATA RS485 IN (PORT 4) (DB-9 FEMALE)

1. (CH.1) INPUT+
2. (CH.1) INPUT-
3. (CH.2) INPUT+
4. (CH.2) INPUT-
5. GND
6. (CH.3) INPUT+
7. (CH.3) INPUT-
8. (CH.4) INPUT+
9. (CH.4) INPUT-



OPTICAL PORT STATUS INDICATORS

1. NA
2. RX OPTICAL SIGNAL (GREEN)/ABSENT (RED)
3. RX CARRIER (GREEN)/ERROR (RED)

STATUS INDICATORS (PORT 3)

1. (CH.1) NA
2. (CH.1) DATA OUTPUT
3. (CH.2) NA
4. (CH.2) DATA OUTPUT
5. (CH.3) NA
6. (CH.3) DATA OUTPUT
7. (CH.4) NA
8. (CH.4) DATA OUTPUT

STATUS INDICATORS (PORT 4)

1. (CH.1) DATA INPUT
2. (CH.1) NA
3. (CH.2) DATA INPUT
4. (CH.2) NA
5. (CH.3) DATA INPUT
6. (CH.3) NA
7. (CH.4) DATA INPUT
8. (CH.4) NA