

FT-1HD2F/2F-12

PINOUT DIAGRAM

COMMON STATUS INDICATORS


PWR - POWER (GREEN)
TX C/L - TX CARRIER (GREEN) / ERROR (RED)
RX C/E - RX CARRIER (GREEN) / ERROR (RED)

VIDEO STATUS INDICATORS

SIG - SDI SIGNAL PRESENT (GREEN)
LAS - SDI LASER (GREEN) / FAIL (RED)
LOC - SDI SIGNAL LOCK (GREEN)
SD - SDI PRESENT (GREEN)
HD - HDSI PRESENT (GREEN)

DATA STATUS INDICATORS

RD1 - (CH.1) DATA INPUT
RD2 - (CH.2) DATA INPUT
TD1 - (CH.1) DATA OUTPUT
TD2 - (CH.2) DATA OUTPUT



OPTICAL PORT (ST, FC)

SDI VIDEO INPUT

PORT 1 RS-422 DATA

1. (CH.2) INPUT+
2. (CH.2) INPUT-
3. (CH.2) OUTPUT+
4. (CH.2) OUTPUT-
5. GND

PORT 2 N/A

PORT 3 RS-422 DATA

1. (CH.1) INPUT+
2. (CH.1) INPUT-
3. (CH.1) OUTPUT+
4. (CH.1) OUTPUT-
5. GND

FR-1HD2F/2F-12

PINOUT DIAGRAM

COMMON STATUS INDICATORS


PWR - POWER (GREEN)
TX C/L - TX CARRIER (GREEN) / ERROR (RED)
RX C/E - RX CARRIER (GREEN) / ERROR (RED)

VIDEO STATUS INDICATORS

SIG - SDI SIGNAL PRESENT (GREEN)
LAS - SDI LASER (GREEN) / FAIL (RED)
LOC - SDI SIGNAL LOCK (GREEN)
SD - SDI PRESENT (GREEN)
HD - HDSI PRESENT (GREEN)

DATA STATUS INDICATORS

RD1 - (CH.1) DATA INPUT
RD2 - (CH.2) DATA INPUT
TD1 - (CH.1) DATA OUTPUT
TD2 - (CH.2) DATA OUTPUT



OPTICAL PORT (ST, FC)

SDI VIDEO OUTPUT

PORT 1 RS-422 DATA

1. (CH.2) INPUT+
2. (CH.2) INPUT-
3. (CH.2) OUTPUT+
4. (CH.2) OUTPUT-
5. GND

PORT 2 N/A

PORT 3 RS-422 DATA

1. (CH.1) INPUT+
2. (CH.1) INPUT-
3. (CH.1) OUTPUT+
4. (CH.1) OUTPUT-
5. GND