

# ST-1HG-X

## PINOUT DIAGRAM

### STATUS INDICATORS

PWR - POWER (GREEN)

DIAG - CARD DIAGNOSTIC (GREEN-OK/RED-ALARM)


LAS/FAIL - (CH.1) LASER (GREEN)/ FAIL (RED)

SIGNAL - (CH.1) SIGNAL PRESENT (GREEN)

SIG LOCK - (CH.1) SIGNAL LOCK (GREEN)

SD LOCK - (CH.1) SDI PRESENT (GREEN)

HD LOCK - (CH.1) HDSDI PRESENT (GREEN)



OPTICAL PORT FC,ST (CH.1)

VIDEO INPUT (CH.1)

VIDEO OUTPUT (CH.1)

# SR-1HG-X

## PINOUT DIAGRAM

### STATUS INDICATORS

PWR - POWER (GREEN)

DIAG - CARD DIAGNOSTIC (GREEN-OK/RED-ALARM)


LOCK/LOSS - (CH.1) LOSS (RED)/ LOCK (GREEN)

0/-5dBm - (CH.1) LEVEL 0/-5dBm (GREEN)

-5/-10dBm - (CH.1) LEVEL -5/-10dBm (GREEN)

-10/-15dBm - (CH.1) LEVEL -10/-15dBm (GREEN)

-15/-20dBm - (CH.1) LEVEL -15/-20dBm (GREEN)



OPTICAL PORT FC,ST (CH.1)

VIDEO OUTPUT (CH.1)

VIDEO OUTPUT (CH.1)