


ST-1W1F/1F-X

PINOUT DIAGRAM

DR1 - (CH.1) DATA OUTPUT
 DR2 - NA
 AR1 - NA
 AR2 - NA
 CR1 - NA
 CR2 - NA
 DT1 - (CH.1) DATA INPUT
 DT2 - NA
 AT1 - NA
 AT2 - NA
 CT1 - NA
 CT2 - NA



OPTICAL PORT (ST, FC)

STATUS INDICATORS

PWR - POWER (GREEN)

DIAG - NA

TX C/L - TX CARRIER (GREEN) / OVERLOAD (RED)

RX C/E - RX CARRIER (GREEN) / ERROR (RED)

VIDEO INPUT

STATUS INDICATORS

SYN - SYNC PRESENT (GREEN)

VID - VIDEO PRESENT (GREEN) / OVERLOAD (RED)


DATA INPUT/OUTPUT

1. (CH.1) DATA INPUT -
2. (CH.1) DATA INPUT +
3. (CH.1) DATA OUTPUT-
4. (CH.1) DATA OUTPUT+
5. GND

SR-1W1F/1F-X

PINOUT DIAGRAM

DR1 - (CH.1) DATA OUTPUT
 DR2 - NA
 AR1 - NA
 AR2 - NA
 CR1 - NA
 CR2 - NA
 DT1 - (CH.1) DATA INPUT
 DT2 - NA
 AT1 - NA
 AT2 - NA
 CT1 - NA
 CT2 - NA



OPTICAL PORT (ST, FC)

STATUS INDICATORS

PWR - POWER (GREEN)

DIAG - NA

TX C/L - TX CARRIER (GREEN) / OVERLOAD (RED)

RX C/E - RX CARRIER (GREEN) / ERROR (RED)

VIDEO OUTPUT

STATUS INDICATORS

SYN - SYNC PRESENT (GREEN)


VID - VIDEO PRESENT (GREEN) / OVERLOAD (RED)

DATA INPUT/OUTPUT

1. (CH.1) DATA INPUT -
2. (CH.1) DATA INPUT +
3. (CH.1) DATA OUTPUT-
4. (CH.1) DATA OUTPUT+
5. GND

SR-1W1F/1F-XD

PINOUT DIAGRAM



OPTICAL PORT <ST, FC>

STATUS INDICATORS

PWR - POWER <GREEN>

DIAG - GREEN-OK, RED-ALARM

TX C/L - TX CARRIER <GREEN> / OVERLOAD <RED>

RX C/E - RX CARRIER <GREEN> / ERROR <RED>

VIDEO OUTPUT

STATUS INDICATORS

SYN - SYNC PRESENT <GREEN>

VID - VIDEO PRESENT <GREEN> / OVERLOAD <RED>

DATA INPUT/OUTPUT

1. <CH.1> DATA INPUT -
2. <CH.1> DATA INPUT +
3. <CH.1> DATA OUTPUT-
4. <CH.1> DATA OUTPUT+
5. GND