

SX-2RE-SFP


PINOUT DIAGRAM

1000 ETHERNET INPUT/OUTPUT CH.1
(RJ-45 FEMALE)

OPTICAL PORT IN/OUT CH.1

1000 ETHERNET INPUT/OUTPUT CH.2
(RJ-45 FEMALE)

OPTICAL PORT IN/OUT CH.2



STATUS INDICATORS

PWR - POWER (GREEN)

DIAG - NA

GREEN STEADY - COPPER CONNECTION ESTABLISHED
FLASHING - COPPER PORT ACTIVITY
OFF - FAULT DETECTED

AMBER STEADY - FIBER CONNECTION ESTABLISHED
FLASHING - FIBER PORT ACTIVITY
OFF - FAULT DETECTED

GREEN STEADY - COPPER CONNECTION ESTABLISHED
FLASHING - COPPER PORT ACTIVITY
OFF - FAULT DETECTED

AMBER STEADY - FIBER CONNECTION ESTABLISHED
FLASHING - FIBER PORT ACTIVITY
OFF - FAULT DETECTED