


PINOUT DIAGRAM



STATUS INDICATORS

DR1 - (CH.1) DATA OUTPUT
DR2 - NA
AR1 - NA
AR2 - NA
CR1 - NA
CR2 - NA
DT1 - (CH.1) DATA INPUT
DT2 - NA
AT1 - NA
AT2 - NA
CT1 - NA
CT2 - NA

OPTICAL PORT (ST, FC)
STATUS INDICATORS

PWR - POWER (GREEN)
DIAG - NA
TX C/L - TX CARRIER (GREEN) / OVERLOAD (RED)
RX C/E - RX CARRIER (GREEN) / ERROR (RED)

SYN - NA
VID - NA

AUDIO N/A

CC N/A

DATA INPUT/OUTPUT

1. (CH.1) RS232 INPUT / RS422 INPUT- / RS485 INPUT-(4W)
RS485 (2W) INPUT/OUTPUT-
2. (CH.1) RS422 INPUT+ / RS485 INPUT+(4W)
RS485 (2W) INPUT/OUTPUT+
3. (CH.1) RS232 OUTPUT / RS422 OUTPUT- / RS485 OUTPUT-(4W)
4. (CH.1) RS422 OUTPUT+ / RS485 OUTPUT+(4W)
5. GND