


SXA/SXB-1J/1J-X

PINOUT DIAGRAM



OPTICAL PORT (ST, FC)

STATUS INDICATORS

PWR - POWER (GREEN)

DIAG - NA

TX C/L - TX CARRIER (GREEN) / OVERLOAD (RED)

RX C/E - RX CARRIER (GREEN) / ERROR (RED)

SYN - NA

VID - NA

DATA INPUT/OUTPUT

1. (CH.1) INPUT/OUTPUT-

2. GND

3. (CH.1) INPUT/OUTPUT+

STATUS INDICATORS

DRX - DATA INPUT/OUTPUT

ARX - NA

CRX - NA